

SUMMARY OF EXPERIENCE

Thirty-one (31) years in Nondestructive Testing and Visual Inspection. I hold the following certifications: AWS Certified Welding Inspector performing project management as a project field coordinator on several projects. ASNT NDT Level III in (UT, MT, PT, RT, VT, ET, ML, IR, LT). ASNT ACCP Professional Level III (UT, MT, PT, RT).

PROFESSIONAL EXPERIENCE

Mayo Consulting Services, LLC- ASNT NDT Level III (UT, MT,PT,RT,VT,ET, ML, IR, LT) – June 2008 to Present

Acuren Inspection Services- NDT Level II Technician – January 2008 to June 2008

RCI Consultants, Inc. – Project Field Coordinator – October 2005 to January 2008

- Newfield Exploration Company – Oversee construction activities for storm damage repairs.
- W&T Offshore – Monitor surveying of overturned platform in West Cameron Area.
- Enterprise – Oversee the loading out of skid packages for SS Block 332.
- Arena Offshore Company – Oversee pipeline installation at EI 58.
- Houston Exploration Company – Oversee caisson fabrication for EC 23 #12.
- Newfield Exploration Company – Oversee meter skid fabrication for ST148.
- Houston Exploration Company – Oversee boat landing fabrication for EC 82B.
- Nippon Exploration Company – Monitor Level II platform inspection at MP 153.
- Magnum Hunter –Oversee ICP fabrication and Installation at MP 207.
- Total E & P –Oversee the ICP fabrication for VK 823.
- MEDCO Energi – Oversee pipeline installation EC 318.
- Total E & P – Oversee fabrication of Pancake section for VK 823.
- Arena Offshore– Beam extension fabrication and installation at Matagorda Island 668.
- MEDCO Energi – Oversee pipeline installation EC 317.
- Arena Offshore– Caisson Deck Fabrication and Installation EC 58.
- Arena Offshore– ICP fabrication and installation EC 58.
- Newfield Exploration Company– Sound Wall Fabrication for WC 580.
- Newfield Exploration Company – Skimmer installation at WC 426.
- Anglo Suisse Offshore – Monitor pipe load out for pipeline for WD 117.
- Newfield Exploration Company – Oversee ICP fabrication for EC 257.

Accurate NDE & Inspection –ASNT NDT Level III Inspector, Welding Inspector – August 2005 to October 2005

- Performed welding inspection and non-destructive testing on offshore structures such as jackets, decks, caissons, process piping and pipelines.

Oceaneering Inspection – ASNT NDT Level III Inspector, Welding Inspector – September 1995 to August 2005

DERRICK MAYO
475 Miller Road
Opelousas, LA 70570
(337)678-1805
mayo9696@yahoo.com

- Performed welding inspection and non-destructive testing on offshore structures such as jackets, decks, caissons, process piping and pipelines.

Bayou Testers – Level II inspector– May 1993 to September 1995

- Performed welding inspection and non-destructive testing on offshore structures such as jackets, decks, caissons, process piping and pipelines.

EBASCO Engineering & Inspection– November 1992 to March 1993

- Performed welding inspection and non-destructive testing on offshore structures such as jackets, decks, caissons, process piping and pipelines.

TRAINING AND CERTIFICATION

- Southern University, Baton Rouge, LA, Civil Engineering
- T.H. Harris Technical College, Opelousas, LA, Nondestructive Testing
- AWS Certified Welding Inspector Preparation Seminar

TRAINING AND CERTIFICATION

- AWS Certified Welding Inspector (Certificate #03020374)
- ASNT NDT Level III Ultrasonic Inspector (Certificate #148577)
- API-RP-2X Certified Ultrasonic Shear wave Inspector
- SNT-TC-1A Level II Radiographic Testing, Dye Penetrant Inspection, Magnetic Particle Inspection